







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE865																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9825166631																																		
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																															
Ticket Type :	Complain	Date & Time :	06-01-2020 07:11:25																																
Vendor Details :																																			
Company Name/Client Name :	Concentrix Services India Pvt Ltd - Alembic	Customer's Mobile :	9825166631	Name :	Amar Sir																														
Address :																																			
gujrat , , , 390003 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	of AXIS Main Entrance (IP Camera - 25) is not working																																		
Technician Comment :	repair ip camera installation and alignment done. now all working properly.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	repair ip camera installation and alignment done. now all working properly.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-01-2020 12:26:08</td><td>ZainulShaikh</td><td>Completed</td><td>repair ip camera installation and alignment done. now all working properly.</td><td></td></tr><tr><td>24-01-2020 01:49:39</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>08-01-2020 11:29:42</td><td>ZainulShaikh</td><td>Awaiting Spares</td><td>bring to office for checking</td><td></td></tr><tr><td>06-01-2020 07:11:33</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>06-01-2020 07:11:25</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-01-2020 12:26:08	ZainulShaikh	Completed	repair ip camera installation and alignment done. now all working properly.		24-01-2020 01:49:39	ZainulShaikh	New		-	08-01-2020 11:29:42	ZainulShaikh	Awaiting Spares	bring to office for checking		06-01-2020 07:11:33	ZainulShaikh	New		-	06-01-2020 07:11:25	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																															
25-01-2020 12:26:08	ZainulShaikh	Completed	repair ip camera installation and alignment done. now all working properly.																																
24-01-2020 01:49:39	ZainulShaikh	New		-																															
08-01-2020 11:29:42	ZainulShaikh	Awaiting Spares	bring to office for checking																																
06-01-2020 07:11:33	ZainulShaikh	New		-																															
06-01-2020 07:11:25	ZainulShaikh	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-12-2020 07:36:19</td><td></td><td></td></tr><tr><td>29-11-2020 10:08:28</td><td></td><td>re-alignment of em lock done</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-12-2020 07:36:19			29-11-2020 10:08:28		re-alignment of em lock done																					
Date Time	Technician Name	Remark																																	
03-12-2020 07:36:19																																			
29-11-2020 10:08:28		re-alignment of em lock done																																	