

B K Infotech

Regd. Office : 506 Swapna Siddhi, Akurli Road, kandivali East Mumbai - 400 064, India.
Support : | W : <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1185																									
Priority :	High																								
Created By :	Admin - Kalpesh Jain																								
Complaint Mob. No. :	8655703325																								
Technician Name :	Shubham Bhojne		Technician Mobile :	9136841707																					
Ticket Type :	New Installation	Date & Time :	09-11-2019 04:44:01																						
Vendor Details :																									
Company Name/Client Name :	Amit Traders	Customer's Mobile :	8655703325	Name :	Amit Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	accessories																								
Complain :	crimping + 24 port switch																								
Technician Comment :	total 38 crompling 24 connector switch install 2 crimp was pending because electrician said me switch side crimp karke rakho dusri side light ke boc mai dala hai nikal ke deta hu par nikal ke nahi diya hai es vajah se																								
Complain Operator :	Desktop - Kalpesh Jain																								
Remark :	total 38 crompling 24 connector switch install 2 crimp was pending because electrician said me switch side crimp karke rakho dusri side light ke boc mai dala hai nikal ke deta hu par nikal ke nahi diya hai es vajah se																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-11-2019 06:20:22</td><td>ShubhamBhojne</td><td>Completed</td><td>total 38 crompling 24 connector switch install 2 crimp was pending because electrician said me switch side crimp karke rakho dusri side light ke boc mai dala hai nikal ke deta hu par nikal ke nahi diya hai es vajah se</td><td></td></tr><tr><td>09-11-2019 04:44:09</td><td>ShubhamBhojne</td><td>New</td><td></td><td>-</td></tr><tr><td>09-11-2019 04:44:01</td><td>ShubhamBhojne</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-11-2019 06:20:22	ShubhamBhojne	Completed	total 38 crompling 24 connector switch install 2 crimp was pending because electrician said me switch side crimp karke rakho dusri side light ke boc mai dala hai nikal ke deta hu par nikal ke nahi diya hai es vajah se		09-11-2019 04:44:09	ShubhamBhojne	New		-	09-11-2019 04:44:01	ShubhamBhojne	New		-
Date Time	Technician Name	Status	Remark	Sign																					
09-11-2019 06:20:22	ShubhamBhojne	Completed	total 38 crompling 24 connector switch install 2 crimp was pending because electrician said me switch side crimp karke rakho dusri side light ke boc mai dala hai nikal ke deta hu par nikal ke nahi diya hai es vajah se																						
09-11-2019 04:44:09	ShubhamBhojne	New		-																					
09-11-2019 04:44:01	ShubhamBhojne	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody></tbody></table>					Date Time	Technician Name	Remark																	
Date Time	Technician Name	Remark																							