

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
 Support : | W : www.vallabhenterprises.com
 E : vallabhsecure@yahoo.co.in

Service Status Details : VE10843																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9137852143																								
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																					
Ticket Type :	Complain	Date & Time :	10-02-2024 04:24:34																						
Vendor Details :																									
Company Name/Client Name :	Tivon Park E/F/G/H Wing	Customer's Mobile :	9137852143	Name :	Ashok Yadav																				
Address :																									
Mumbai , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	f wing DVR end dressing need to do																								
Technician Comment :	F/G/H and sales office dvr dressing done G wing 2 camera off issue resolved working ok and 2 camera angle seting done Sales office 2 camera angle seting done And back gate 1 camera broken																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	F/G/H and sales office dvr dressing done G wing 2 camera off issue resolved working ok and 2 camera angle seting done Sales office 2 camera angle seting done And back gate 1 camera broken																								
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>28-02-2024 04:55:56</td> <td>Sonu Kumar</td> <td>Completed</td> <td>F/G/H and sales office dvr dressing done G wing 2 camera off issue resolved working ok and 2 camera angle seting done Sales office 2 camera angle seting done And back gate 1 camera broken</td> <td></td> </tr> <tr> <td>28-02-2024 11:20:29</td> <td>Sonu Kumar</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>12-02-2024 04:15:25</td> <td>Sonu Kumar</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	28-02-2024 04:55:56	Sonu Kumar	Completed	F/G/H and sales office dvr dressing done G wing 2 camera off issue resolved working ok and 2 camera angle seting done Sales office 2 camera angle seting done And back gate 1 camera broken		28-02-2024 11:20:29	Sonu Kumar	New		-	12-02-2024 04:15:25	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
28-02-2024 04:55:56	Sonu Kumar	Completed	F/G/H and sales office dvr dressing done G wing 2 camera off issue resolved working ok and 2 camera angle seting done Sales office 2 camera angle seting done And back gate 1 camera broken																						
28-02-2024 11:20:29	Sonu Kumar	New		-																					
12-02-2024 04:15:25	Sonu Kumar	New		-																					
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>22-02-2024 11:44:56</td> <td>Atique Salmani</td> <td>One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.</td> </tr> <tr> <td>21-02-2024 11:22:58</td> <td>PravinJagade</td> <td>G wing recording check done</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.	21-02-2024 11:22:58	PravinJagade	G wing recording check done											
Date Time	Technician Name	Remark																							
22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																							
21-02-2024 11:22:58	PravinJagade	G wing recording check done																							