

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10931																				
Priority :		Low																		
Created By :		Admin - Apurva Vajaria																		
Complaint Mob. No. :		9137852143																		
Technician Name :		Pravin Jagade		Technician Mobile :	7262044153															
Ticket Type :		Complain	Date & Time :		21-02-2024 11:22:58															
Vendor Details :																				
Company Name/Client Name :		Tivon Park E/F/G/H Wing	Customer's Mobile :	9137852143	Name : Ashok Yadav															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :		01-01-1970 05:30:00		Type :																
Product Name :		CCTV																		
Complain :		need to check the recording in G wing																		
Technician Comment :																				
Complain Operator :		Desktop - Apurva Vajaria																		
Remark :		G wing recording check done																		
Status History :		<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-02-2024 03:45:18</td><td>PravinJagade</td><td>Completed</td><td></td><td>-</td></tr><tr><td>21-02-2024 11:25:28</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>				Date Time	Technician Name	Status	Remark	Sign	23-02-2024 03:45:18	PravinJagade	Completed		-	21-02-2024 11:25:28	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
23-02-2024 03:45:18	PravinJagade	Completed		-																
21-02-2024 11:25:28	PravinJagade	New		-																
Previous Complain History :		<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-02-2024 11:44:56</td><td>Atique Salmani</td><td>One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.</td></tr><tr><td>10-02-2024 04:24:34</td><td></td><td></td></tr></tbody></table>				Date Time	Technician Name	Remark	22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.	10-02-2024 04:24:34								
Date Time	Technician Name	Remark																		
22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																		
10-02-2024 04:24:34																				