




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10941																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9137852143																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	22-02-2024 11:44:56																	
Vendor Details :																				
Company Name/Client Name :	Tivon Park E/F/G/H Wing	Customer's Mobile :	9137852143	Name :	Ashok Yadav															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Common car parking area 2 camera off issue																			
Technician Comment :	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-02-2024 05:43:43</td><td>Atique Salmani</td><td>Completed</td><td>One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.</td><td></td></tr><tr><td>22-02-2024 11:45:05</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-02-2024 05:43:43	Atique Salmani	Completed	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.		22-02-2024 11:45:05	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
22-02-2024 05:43:43	Atique Salmani	Completed	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																	
22-02-2024 11:45:05	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-02-2024 11:22:58</td><td>PravinJagade</td><td>G wing recording check done</td></tr><tr><td>10-02-2024 04:24:34</td><td></td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	21-02-2024 11:22:58	PravinJagade	G wing recording check done	10-02-2024 04:24:34								
Date Time	Technician Name	Remark																		
21-02-2024 11:22:58	PravinJagade	G wing recording check done																		
10-02-2024 04:24:34																				