

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11364																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9137852143																								
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																					
Ticket Type :	Complain	Date & Time :	12-04-2024 01:07:44																						
Vendor Details :																									
Company Name/Client Name :	Tivon Park E/F/G/H Wing	Customer's Mobile :	9137852143	Name :	Ashok Yadav																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	main gate camera angle issue																								
Technician Comment :	1 camera angle seting done																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1 camera angle seting done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-04-2024 12:57:41</td><td>Sonu Kumar</td><td>Completed</td><td>1 camera angle seting done</td><td></td></tr><tr><td>15-04-2024 10:07:25</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-04-2024 10:26:30</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-04-2024 12:57:41	Sonu Kumar	Completed	1 camera angle seting done		15-04-2024 10:07:25	Sonu Kumar	New		-	13-04-2024 10:26:30	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
15-04-2024 12:57:41	Sonu Kumar	Completed	1 camera angle seting done																						
15-04-2024 10:07:25	Sonu Kumar	New		-																					
13-04-2024 10:26:30	Sonu Kumar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-03-2024 12:11:42</td><td></td><td></td></tr><tr><td>22-02-2024 11:44:56</td><td>Atique Salmani</td><td>One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-03-2024 12:11:42			22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.											
Date Time	Technician Name	Remark																							
26-03-2024 12:11:42																									
22-02-2024 11:44:56	Atique Salmani	One camera car parking area issue resolved working ok camera female connector was rishted so direct it working ok.																							