




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12385																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9137852143																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	Complain	Date & Time :	09-08-2024 11:37:06																	
Vendor Details :																				
Company Name/Client Name :	Tivon Park E/F/G/H Wing	Customer's Mobile :	9137852143	Name :	Ashok Yadav															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	G and F wing lift camera not working																			
Technician Comment :	F wing lift camera cable joint camera working ok and G wing bnc connector change camera working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	F wing lift camera cable joint camera working ok and G wing bnc connector change camera working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-08-2024 01:04:46</td><td>Sonu Kumar</td><td>Completed</td><td>F wing lift camera cable joint camera working ok and G wing bnc connector change camera working ok</td><td></td></tr><tr><td>12-08-2024 10:24:41</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-08-2024 01:04:46	Sonu Kumar	Completed	F wing lift camera cable joint camera working ok and G wing bnc connector change camera working ok		12-08-2024 10:24:41	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-08-2024 01:04:46	Sonu Kumar	Completed	F wing lift camera cable joint camera working ok and G wing bnc connector change camera working ok																	
12-08-2024 10:24:41	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-08-2024 01:26:12</td><td></td><td></td></tr><tr><td>06-08-2024 02:52:08</td><td>Sonu Kumar</td><td>Dvr shifted in sample flat H104 10 MTR , install all three camera working ok but main gate camera water fallen need to change</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-08-2024 01:26:12			06-08-2024 02:52:08	Sonu Kumar	Dvr shifted in sample flat H104 10 MTR , install all three camera working ok but main gate camera water fallen need to change						
Date Time	Technician Name	Remark																		
14-08-2024 01:26:12																				
06-08-2024 02:52:08	Sonu Kumar	Dvr shifted in sample flat H104 10 MTR , install all three camera working ok but main gate camera water fallen need to change																		