

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4452																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7738881588																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	23-12-2021 10:38:28																						
Vendor Details :																									
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	7738881588	Name :	Aziza Madam																				
Address :																									
Mumbai , , , 400064 , Maharashtra																									
AMC Details :																									
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	VDP																								
Complain :	1402 VDP issue																								
Technician Comment :	intercom isse resolved working ok vdp duct supply faulty need to changed .after approval .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	intercom isse resolved working ok vdp duct supply faulty need to changed .after approval .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-12-2021 10:40:29</td><td>Atique Salmani</td><td>Completed</td><td>intercom isse resolved working ok vdp duct supply faulty need to changed .after approval .</td><td></td></tr><tr><td>23-12-2021 10:38:52</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>23-12-2021 10:38:28</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-12-2021 10:40:29	Atique Salmani	Completed	intercom isse resolved working ok vdp duct supply faulty need to changed .after approval .		23-12-2021 10:38:52	Atique Salmani	New		-	23-12-2021 10:38:28	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-12-2021 10:40:29	Atique Salmani	Completed	intercom isse resolved working ok vdp duct supply faulty need to changed .after approval .																						
23-12-2021 10:38:52	Atique Salmani	New		-																					
23-12-2021 10:38:28	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-01-2022 04:42:50</td><td>Atique Salmani</td><td>make check list and all flor cameras check all working ok ppm done .</td></tr><tr><td>15-01-2022 04:41:19</td><td>Atique Salmani</td><td>1902 line ok instrument issue some notice issue and 3 cameras issue resolved all working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-01-2022 04:42:50	Atique Salmani	make check list and all flor cameras check all working ok ppm done .	15-01-2022 04:41:19	Atique Salmani	1902 line ok instrument issue some notice issue and 3 cameras issue resolved all working ok.											
Date Time	Technician Name	Remark																							
15-01-2022 04:42:50	Atique Salmani	make check list and all flor cameras check all working ok ppm done .																							
15-01-2022 04:41:19	Atique Salmani	1902 line ok instrument issue some notice issue and 3 cameras issue resolved all working ok.																							