

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8748																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9158640778																			
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																
Ticket Type :	Complain	Date & Time :	05-07-2023 10:07:51																	
Vendor Details :																				
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9158640778	Name :	Aziza Madam															
Address :																				
Mumbai , , , 400064 , Maharashtra																				
AMC Details :																				
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	cCTV-Intercom																			
Complain :	flat no. 401 intercom issue and backside 1 camera off issue																			
Technician Comment :	Camera No.6 Back Side Problem Solved. 401 System Side Line Check Line OK (Flat Lock)																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Camera No.6 Back Side Problem Solved. 401 System Side Line Check Line OK (Flat Lock)																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2023 03:29:50</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Camera No.6 Back Side Problem Solved. 401 System Side Line Check Line OK (Flat Lock)</td><td></td></tr><tr><td>05-07-2023 10:08:04</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2023 03:29:50	Kalpesh SubhashGurav	Completed	Camera No.6 Back Side Problem Solved. 401 System Side Line Check Line OK (Flat Lock)		05-07-2023 10:08:04	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-07-2023 03:29:50	Kalpesh SubhashGurav	Completed	Camera No.6 Back Side Problem Solved. 401 System Side Line Check Line OK (Flat Lock)																	
05-07-2023 10:08:04	Kalpesh SubhashGurav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>4 TB HDD Abnormal So Collect HDD For Reapir Our Service Center.</td></tr><tr><td>12-07-2023 01:07:59</td><td>Ravi Rajbhar</td><td>need to done off cctv sarvey 3 camera two gym and one hall cabling 100- 150 metr dvr / nvr luction society office</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-07-2023 10:29:11	Kalpesh SubhashGurav	4 TB HDD Abnormal So Collect HDD For Reapir Our Service Center.	12-07-2023 01:07:59	Ravi Rajbhar	need to done off cctv sarvey 3 camera two gym and one hall cabling 100- 150 metr dvr / nvr luction society office						
Date Time	Technician Name	Remark																		
15-07-2023 10:29:11	Kalpesh SubhashGurav	4 TB HDD Abnormal So Collect HDD For Reapir Our Service Center.																		
12-07-2023 01:07:59	Ravi Rajbhar	need to done off cctv sarvey 3 camera two gym and one hall cabling 100- 150 metr dvr / nvr luction society office																		