

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7781															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	8369359090														
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153											
Ticket Type :	AMC visiting	Date & Time :	04-03-2023 11:24:06												
Vendor Details :															
Company Name/Client Name :	Gomti Co Op Hsg Society	Customer's Mobile :	8369359090	Name :	Bharat Purohit										
Address :															
Mumbai , Mandpeshwar Road, Divine Home Colony, Navagaon, Dahisar West, Mumbai, Maharashtra, India , , , Maharashtra															
AMC Details :															
Expiry Date :	18-12-2020 12:00:00		Type :	Non-Comprehensive											
Product Name :	Ppm														
Complain :	need to do cctv ppm														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-03-2023 11:24:20</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-03-2023 11:24:20	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign											
04-03-2023 11:24:20	PravinJagade	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2023 12:24:31</td><td>PravinJagade</td><td>A wing parking area camera sifting done. 10 min recording client wp no send. Work complete</td></tr><tr><td>05-07-2023 09:57:48</td><td>Kalpesh SubhashGurav</td><td>camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete	05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm	
Date Time	Technician Name	Remark													
10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete													
05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm													