




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE831																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8369359090																								
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																					
Ticket Type :	Complain	Date & Time :	24-12-2019 02:22:16																						
Vendor Details :																									
Company Name/Client Name :	Gomti Co Op Hsg Society	Customer's Mobile :	8369359090	Name :	Bharat Purohit																				
Address :																									
Mumbai , Mandpeshwar Road, Divine Home Colony, Navagaon, Dahisar West, Mumbai, Maharashtra, India , , , Maharashtra																									
AMC Details :																									
Expiry Date :	18-12-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	need to show recording																								
Technician Comment :	backup given to client 15/12/19-16:55_15/12/19-17:35																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	backup given to client 15/12/19-16:55_15/12/19-17:35																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-12-2019 07:03:58</td><td>MayurYadav</td><td>Completed</td><td>backup given to client 15/12/19-16:55_15/12/19-17:35</td><td></td></tr><tr><td>24-12-2019 02:22:24</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>24-12-2019 02:22:17</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-12-2019 07:03:58	MayurYadav	Completed	backup given to client 15/12/19-16:55_15/12/19-17:35		24-12-2019 02:22:24	MayurYadav	New		-	24-12-2019 02:22:17	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-12-2019 07:03:58	MayurYadav	Completed	backup given to client 15/12/19-16:55_15/12/19-17:35																						
24-12-2019 02:22:24	MayurYadav	New		-																					
24-12-2019 02:22:17	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2023 12:24:31</td><td>PravinJagade</td><td>A wing parking area camera sifting done. 10 min recording client wp no send. Work complete</td></tr><tr><td>05-07-2023 09:57:48</td><td>Kalpesh SubhashGurav</td><td>camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete	05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm											
Date Time	Technician Name	Remark																							
10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete																							
05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm																							