




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8745																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8369359090																			
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																
Ticket Type :	Complain	Date & Time :	05-07-2023 09:57:48																	
Vendor Details :																				
Company Name/Client Name :	Gomti Co Op Hsg Society	Customer's Mobile :	8369359090	Name :	Bharat Purohit															
Address :																				
Mumbai , Mandpeshwar Road, Divine Home Colony, Navagaon, Dahisar West, Mumbai, Maharashtra, India , , , Maharashtra																				
AMC Details :																				
Expiry Date :	18-12-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	need to show recording																			
Technician Comment :	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2023 12:01:04</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm</td><td></td></tr><tr><td>05-07-2023 09:57:54</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2023 12:01:04	Kalpesh SubhashGurav	Completed	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm		05-07-2023 09:57:54	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-07-2023 12:01:04	Kalpesh SubhashGurav	Completed	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm																	
05-07-2023 09:57:54	Kalpesh SubhashGurav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2023 12:24:31</td><td>PravinJagade</td><td>A wing parking area camera sifting done. 10 min recording client wp no send. Work complete</td></tr><tr><td>07-06-2023 12:39:12</td><td>Kalpesh SubhashGurav</td><td>PPM Done. All Camera Servicing Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete	07-06-2023 12:39:12	Kalpesh SubhashGurav	PPM Done. All Camera Servicing Done.						
Date Time	Technician Name	Remark																		
10-07-2023 12:24:31	PravinJagade	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete																		
07-06-2023 12:39:12	Kalpesh SubhashGurav	PPM Done. All Camera Servicing Done.																		