




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8788</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	8369359090																			
<b>Technician Name :</b>	Pravin Jagade		<b>Technician Mobile :</b>	7262044153																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-07-2023 12:24:31																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Gomti Co Op Hsg Society	<b>Customer's Mobile :</b>	8369359090	<b>Name :</b>	Bharat Purohit															
<b>Address :</b>																				
Mumbai , Mandpeshwar Road, Divine Home Colony, Navagaon, Dahisar West, Mumbai, Maharashtra, India , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	18-12-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	A wing front parking area camera need to shift																			
<b>Technician Comment :</b>	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-07-2023 03:29:46</td><td>PravinJagade</td><td>Completed</td><td>A wing parking area camera sifting done. 10 min recording client wp no send. Work complete</td><td></td></tr><tr><td>10-07-2023 12:24:50</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-07-2023 03:29:46	PravinJagade	Completed	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete		10-07-2023 12:24:50	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-07-2023 03:29:46	PravinJagade	Completed	A wing parking area camera sifting done. 10 min recording client wp no send. Work complete																	
10-07-2023 12:24:50	PravinJagade	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-07-2023 09:57:48</td><td>Kalpesh SubhashGurav</td><td>camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm</td></tr><tr><td>07-06-2023 12:39:12</td><td>Kalpesh SubhashGurav</td><td>PPM Done. All Camera Servicing Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm	07-06-2023 12:39:12	Kalpesh SubhashGurav	PPM Done. All Camera Servicing Done.						
Date Time	Technician Name	Remark																		
05-07-2023 09:57:48	Kalpesh SubhashGurav	camera No.5 has to be shifted due to water falling on it. Camera No.6 Recording Given Date 02/07/2023 Time 11:02 pm																		
07-06-2023 12:39:12	Kalpesh SubhashGurav	PPM Done. All Camera Servicing Done.																		