




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8115																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8779909151																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	15-04-2023 10:36:28																	
Vendor Details :																				
Company Name/Client Name :	Damji Shamji - Tivon Park E Wing	Customer's Mobile :	8779909151	Name :	Bhavesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	not able to see recording need to check																			
Technician Comment :	E wing required material USB male femal cable 5 meter and mouse for check recording.and how to check regarding told to Sunil ji and also security person And sales office hdmi splitter faulty and extender is also blinking and fractuate . So painding.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	E wing required material USB male femal cable 5 meter and mouse for check recording.and how to check regarding told to Sunil ji and also security person And sales office hdmi splitter faulty and extender is also blinking and fractuate . So painding.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-04-2023 12:03:11</td><td>Atique Salmani</td><td>Work Pending</td><td>E wing required material USB male femal cable 5 meter and mouse for check recording.and how to check regarding told to Sunil ji and also security person And sales office hdmi splitter faulty and extender is also blinking and fractuate . So painding.</td><td></td></tr><tr><td>15-04-2023 10:36:55</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-04-2023 12:03:11	Atique Salmani	Work Pending	E wing required material USB male femal cable 5 meter and mouse for check recording.and how to check regarding told to Sunil ji and also security person And sales office hdmi splitter faulty and extender is also blinking and fractuate . So painding.		15-04-2023 10:36:55	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
15-04-2023 12:03:11	Atique Salmani	Work Pending	E wing required material USB male femal cable 5 meter and mouse for check recording.and how to check regarding told to Sunil ji and also security person And sales office hdmi splitter faulty and extender is also blinking and fractuate . So painding.																	
15-04-2023 10:36:55	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-07-2023 10:52:34</td><td>PravinJagade</td><td>E wing camera no video issue resolve working done. And parking camera no video issue resolve.</td></tr><tr><td>17-03-2023 04:17:40</td><td>SantoshPathak</td><td>Kalpesh visited 17.03.2023 - E wing 102, 002/ E wing 3/4 Line ok beetel two telephone handover E/201 - Beetel telephone installed carpenter sign</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-07-2023 10:52:34	PravinJagade	E wing camera no video issue resolve working done. And parking camera no video issue resolve.	17-03-2023 04:17:40	SantoshPathak	Kalpesh visited 17.03.2023 - E wing 102, 002/ E wing 3/4 Line ok beetel two telephone handover E/201 - Beetel telephone installed carpenter sign						
Date Time	Technician Name	Remark																		
19-07-2023 10:52:34	PravinJagade	E wing camera no video issue resolve working done. And parking camera no video issue resolve.																		
17-03-2023 04:17:40	SantoshPathak	Kalpesh visited 17.03.2023 - E wing 102, 002/ E wing 3/4 Line ok beetel two telephone handover E/201 - Beetel telephone installed carpenter sign																		