

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14465															
Priority :		Low													
Created By :		Admin - Apurva Vajaria													
Complaint Mob. No. :		9821013611													
Technician Name :		Maroof Raza		Technician Mobile :	7761863562										
Ticket Type :		Complain	Date & Time :	10-04-2025 11:53:36											
Vendor Details :															
Company Name/Client Name :		Havelli Kandiwali	Customer's Mobile :	9821013611	Name : Bhikhu Bhai										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :		01-01-1970 05:30:00		Type :											
Product Name :		CCTV													
Complain :		One camera need to install and cabling need to do													
Technician Comment :															
Complain Operator :		Desktop - Apurva Vajaria													
Remark :		One camera need to installation and cabling done													
Status History :		<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-04-2025 11:53:55</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr></tbody></table>				Date Time	Technician Name	Status	Remark	Sign	10-04-2025 11:53:55	MaroofRaza	New		-
Date Time	Technician Name	Status	Remark	Sign											
10-04-2025 11:53:55	MaroofRaza	New		-											
Previous Complain History :		<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-10-2024 11:40:24</td><td>AnkitKumar</td><td>Work panding Reason : 35 to 40 meter wire has to be inserted, head and camera have to be a changed</td></tr><tr><td>24-04-2024 11:22:06</td><td>PrashantSaroj</td><td>1 camera shifting done</td></tr></tbody></table>				Date Time	Technician Name	Remark	07-10-2024 11:40:24	AnkitKumar	Work panding Reason : 35 to 40 meter wire has to be inserted, head and camera have to be a changed	24-04-2024 11:22:06	PrashantSaroj	1 camera shifting done	
Date Time	Technician Name	Remark													
07-10-2024 11:40:24	AnkitKumar	Work panding Reason : 35 to 40 meter wire has to be inserted, head and camera have to be a changed													
24-04-2024 11:22:06	PrashantSaroj	1 camera shifting done													