




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1932																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9224657132																								
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																					
Ticket Type :	Complain	Date & Time :	01-10-2020 11:20:18																						
Vendor Details :																									
Company Name/Client Name :	Bhoomi Association	Customer's Mobile :	9224657132	Name :	Bipin Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	1 camera off																								
Technician Comment :	camera female cnetor damge and connector cutting and direct jointing and camera working OK																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	camera female cnetor damge and connector cutting and direct jointing and camera working OK																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-10-2020 12:16:42</td><td>Neeraj Chauhan</td><td>Completed</td><td>camera female cnetor damge and connector cutting and direct jointing and camera working OK</td><td></td></tr><tr><td>01-10-2020 11:20:32</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2020 11:20:19</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-10-2020 12:16:42	Neeraj Chauhan	Completed	camera female cnetor damge and connector cutting and direct jointing and camera working OK		01-10-2020 11:20:32	Neeraj Chauhan	New		-	01-10-2020 11:20:19	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
01-10-2020 12:16:42	Neeraj Chauhan	Completed	camera female cnetor damge and connector cutting and direct jointing and camera working OK																						
01-10-2020 11:20:32	Neeraj Chauhan	New		-																					
01-10-2020 11:20:19	Neeraj Chauhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-05-2023 11:55:55</td><td>Siddhesh Chavan</td><td>4camera recoding off issue and recoding not found and reonrecording</td></tr><tr><td>04-05-2023 11:36:03</td><td>Shiva Meena</td><td>3 parsan finger add and work complete</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-05-2023 11:55:55	Siddhesh Chavan	4camera recoding off issue and recoding not found and reonrecording	04-05-2023 11:36:03	Shiva Meena	3 parsan finger add and work complete											
Date Time	Technician Name	Remark																							
31-05-2023 11:55:55	Siddhesh Chavan	4camera recoding off issue and recoding not found and reonrecording																							
04-05-2023 11:36:03	Shiva Meena	3 parsan finger add and work complete																							