


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6333</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9884958343				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-09-2022 10:54:23		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Bombay Deyng And Manufacturing Co. Ltd	<b>Customer's Mobile :</b>	9884958343	<b>Name :</b>	Chandraraja Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	31-07-2020 12:00:00		<b>Type :</b>	Comprehensive	
<b>Product Name :</b>	CCTV				
<b>Complain :</b>	camera need to install and audio camera need to check not able to hear nvr need to be viewed via lan in rajiv sir laptop				
<b>Technician Comment :</b>	Ptz camera installation done angel settings done 2 hose clip 4*4 boxes Vedio baloon use material working ok Smpls of ptz camera installed above maintance room cable tray And 1st floor staircase reception ground and exit door cameras fractuating so use SMPS wich one remooved from main gate pole camera working ok SMPS use 1floor duct . Also audio main stream and substraem on and also download gaurd station apps in rajiv sir laptop All working ok .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	Ptz camera installation done angel settings done 2 hose clip 4*4 boxes Vedio baloon use material working ok Smpls of ptz camera installed above maintance room cable tray And 1st floor staircase reception ground and exit door cameras fractuating so use SMPS wich one remooved from main gate pole camera working ok SMPS use 1floor duct . Also audio main stream and substraem on and also download gaurd station apps in rajiv sir laptop All working ok .				

<b>Status History :</b>	Date Time	Technician Name	Status	Remark	Sign
	08-09-2022 06:26:37	Atique Salmani	Completed	Ptz camera installation done angel settings done 2 hose clip 4*4 boxes Vedio baloon use material working ok Smpls of ptz camera installed above maintance room cable tray And 1st floor staircase reception ground and exit door cameras fractuating so use SMPS wich one remooved from main gate pole camera working ok SMPS use 1floor duct . Also audio main stream and substraem on and also download gaurd station apps in rajiv sir laptop All working ok .	
	08-09-2022 10:54:55	Atique Salmani	New		-
	08-09-2022 10:54:24	Atique Salmani	New		-
<b>Previous Complain History :</b>	Date Time	Technician Name	Remark		
	02-08-2022 12:39:06	Anil Yadav			
	23-07-2022 10:11:41	Atique Salmani	dvr 2 19 cameras recording 56 days and dvr 1 44 days and 3 cameras sheet changed and camera reinstalled also angel settings done. second floor south side give external SMPS so when light off 4 cameras going off so give direct 230 to SMPS by maintenance persone issue resolved.		