

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11851																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9810080819																			
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																
Ticket Type :	Call Basis	Date & Time :	08-06-2024 12:18:45																	
Vendor Details :																				
Company Name/Client Name :	Neil J Control	Customer's Mobile :	9810080819	Name :	Dabral Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Site: Lalit hotel - 3-4 cameras off issue																			
Technician Comment :	5 ip camera work and 2 analog camera work and cebaling 104 miter work complete																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	5 ip camera work and 2 analog camera work and cebaling 104 miter work complete																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2024 06:14:18</td><td>Shiva Meena</td><td>Completed</td><td>5 ip camera work and 2 analog camera work and cebaling 104 miter work complete</td><td></td></tr><tr><td>10-06-2024 10:32:03</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2024 06:14:18	Shiva Meena	Completed	5 ip camera work and 2 analog camera work and cebaling 104 miter work complete		10-06-2024 10:32:03	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-06-2024 06:14:18	Shiva Meena	Completed	5 ip camera work and 2 analog camera work and cebaling 104 miter work complete																	
10-06-2024 10:32:03	Shiva Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-06-2024 04:09:17</td><td></td><td></td></tr><tr><td>21-06-2024 10:24:55</td><td>Sonu Kumar</td><td>Main gate 2 camera off issue resolved working ok and out gate camera off issue resolved working ok and 1 □□□□ op configuration done and main gate 26 MTR</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-06-2024 04:09:17			21-06-2024 10:24:55	Sonu Kumar	Main gate 2 camera off issue resolved working ok and out gate camera off issue resolved working ok and 1 □□□□ op configuration done and main gate 26 MTR						
Date Time	Technician Name	Remark																		
29-06-2024 04:09:17																				
21-06-2024 10:24:55	Sonu Kumar	Main gate 2 camera off issue resolved working ok and out gate camera off issue resolved working ok and 1 □□□□ op configuration done and main gate 26 MTR																		