Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	ails: VE529					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9870067773					
Technician Name	Anil Yadav		Technicia:	an Mobile 8080922983		
Ticket Type :	New Installation	Date & Time :	17-10-2019 01:41:22			
Vendor Details :						
Company Name/Client Name :	Scheitel Security Systems	Customer's Mobile :	9870067773 Name:		Dharmil Shah	
Address:						
Mumbai , , , , Mah	arashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:00	0	Type:			
Product Name:	Alarm System					
Complain:	8 zone pane installation with detectors and sensors					
Technician Comment :	8 zone panel,two multi glass detectors,two door sencer installed. hooter pending because client should little hooter.					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	8 zone panel,two multi glass detectors,two door sencer installed. hooter pending because client should little hooter.					
Status History:	Date Time	Technician Name	Status	Remark		Sign
	23-10-2019 01:52:39	AnilYadav	Completed	8 zone panel,two multi glass detectors,two door sencer installed. hooter pending because client should little hooter.		2
	17-10-2019 03:52:13	AnilYadav	New			-
	17-10-2019 01:41:22	AnilYadav	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permently and panel cancter press and panel issue resolved			
	20-07-2021 06:43:21	MayurYadav	intrusion zone reconnection and bypass at panel side keep under observation			