

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7796																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9820536525																													
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																										
Ticket Type :	Complain	Date & Time :	06-03-2023 01:35:47																											
Vendor Details :																														
Company Name/Client Name :	Vireshwar Heights	Customer's Mobile :	9820536525	Name :	Dhiru Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Intercom																													
Complain :	601 - security when calling to flat low ring issue																													
Technician Comment :	601 new instrument install and ok working done Old video door phone remove and hondover to client																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	601 new instrument install and ok working done Old video door phone remove and hondover to client																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-03-2023 03:54:23</td><td>Ravi Rajbhar</td><td>Completed</td><td>601 new instrument install and ok working done Old video door phone remove and hondover to client</td><td></td></tr><tr><td>08-03-2023 11:37:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>06-03-2023 03:00:10</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>Commax vdp ringer issue need to changed new instrument line ok.</td><td></td></tr><tr><td>06-03-2023 01:35:56</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-03-2023 03:54:23	Ravi Rajbhar	Completed	601 new instrument install and ok working done Old video door phone remove and hondover to client		08-03-2023 11:37:01	Ravi Rajbhar	New		-	06-03-2023 03:00:10	Ravi Rajbhar	Work Pending	Commax vdp ringer issue need to changed new instrument line ok.		06-03-2023 01:35:56	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
08-03-2023 03:54:23	Ravi Rajbhar	Completed	601 new instrument install and ok working done Old video door phone remove and hondover to client																											
08-03-2023 11:37:01	Ravi Rajbhar	New		-																										
06-03-2023 03:00:10	Ravi Rajbhar	Work Pending	Commax vdp ringer issue need to changed new instrument line ok.																											
06-03-2023 01:35:56	Ravi Rajbhar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-03-2023 02:23:00</td><td>Atique Salmani</td><td></td></tr><tr><td>11-03-2023 11:07:16</td><td>Sonu Kumar</td><td>Mount table phone installed working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	11-03-2023 02:23:00	Atique Salmani		11-03-2023 11:07:16	Sonu Kumar	Mount table phone installed working ok																
Date Time	Technician Name	Remark																												
11-03-2023 02:23:00	Atique Salmani																													
11-03-2023 11:07:16	Sonu Kumar	Mount table phone installed working ok																												