




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10</b>																				
<b>Priority :</b>	High																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	8451099978																			
<b>Technician Name :</b>	Zainul Shaikh		<b>Technician Mobile :</b>	8080922971																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-08-2019 01:14:01																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Dev Research Centre	<b>Customer's Mobile :</b>	8451099978	<b>Name :</b>	Hitesh Doshi															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	Bill submission and show material installed at which location																			
<b>Technician Comment :</b>	all process done.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	all process done.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-08-2019 01:38:44</td><td>ZainulShaikh</td><td>Completed</td><td>all process done.</td><td></td></tr><tr><td>10-08-2019 01:14:02</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-08-2019 01:38:44	ZainulShaikh	Completed	all process done.		10-08-2019 01:14:02	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																
16-08-2019 01:38:44	ZainulShaikh	Completed	all process done.																	
10-08-2019 01:14:02	ZainulShaikh	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-11-2019 11:48:23</td><td>ZainulShaikh</td><td></td></tr><tr><td>13-08-2019 07:21:01</td><td>ZainulShaikh</td><td>One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-11-2019 11:48:23	ZainulShaikh		13-08-2019 07:21:01	ZainulShaikh	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.						
Date Time	Technician Name	Remark																		
04-11-2019 11:48:23	ZainulShaikh																			
13-08-2019 07:21:01	ZainulShaikh	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.																		