




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE47																				
Priority :	High																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8451099978																			
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																
Ticket Type :	Complain	Date & Time :	13-08-2019 07:21:01																	
Vendor Details :																				
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	1 camera not working																			
Technician Comment :	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.																			
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>16-08-2019 01:38:05</td> <td>ZainulShaikh</td> <td>Completed</td> <td>One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.</td> <td></td> </tr> <tr> <td>13-08-2019 07:21:01</td> <td>ZainulShaikh</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	16-08-2019 01:38:05	ZainulShaikh	Completed	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.		13-08-2019 07:21:01	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																
16-08-2019 01:38:05	ZainulShaikh	Completed	One gate side camera Changed and installed with 4x4 box now working ok. one 4 channel dvr camera Power supply changed now working ok. one 3rd flr conference room live view and recording stop as per client information. one 3rd flr smoke detector cleaning done properly working ok now under observation.																	
13-08-2019 07:21:01	ZainulShaikh	New		-																
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>04-11-2019 11:48:23</td> <td>ZainulShaikh</td> <td></td> </tr> <tr> <td>10-08-2019 01:14:01</td> <td>ZainulShaikh</td> <td>all process done.</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	04-11-2019 11:48:23	ZainulShaikh		10-08-2019 01:14:01	ZainulShaikh	all process done.						
Date Time	Technician Name	Remark																		
04-11-2019 11:48:23	ZainulShaikh																			
10-08-2019 01:14:01	ZainulShaikh	all process done.																		