







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8478																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8451099978																													
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																										
Ticket Type :	Complain	Date & Time :	02-06-2023 12:02:49																											
Vendor Details :																														
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	06-06-2021 12:00:00		Type :	Comprehensive																										
Product Name :	EPABX																													
Complain :	EPABX issue need to check																													
Technician Comment :	Repair Power Supply Installed Done System working ok																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Repair Power Supply Installed Done System working ok																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2023 12:38:13</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Repair Power Supply Installed Done System working ok</td><td></td></tr><tr><td>10-06-2023 11:05:23</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr><tr><td>02-06-2023 12:55:15</td><td>Kalpesh SubhashGurav</td><td>Awaiting Spares</td><td>System Power Supply Issue Power Supply Collect For Repair.</td><td></td></tr><tr><td>02-06-2023 12:03:26</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2023 12:38:13	Kalpesh SubhashGurav	Completed	Repair Power Supply Installed Done System working ok		10-06-2023 11:05:23	Kalpesh SubhashGurav	New		-	02-06-2023 12:55:15	Kalpesh SubhashGurav	Awaiting Spares	System Power Supply Issue Power Supply Collect For Repair.		02-06-2023 12:03:26	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																										
10-06-2023 12:38:13	Kalpesh SubhashGurav	Completed	Repair Power Supply Installed Done System working ok																											
10-06-2023 11:05:23	Kalpesh SubhashGurav	New		-																										
02-06-2023 12:55:15	Kalpesh SubhashGurav	Awaiting Spares	System Power Supply Issue Power Supply Collect For Repair.																											
02-06-2023 12:03:26	Kalpesh SubhashGurav	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-02-2023 02:46:16</td><td>ChandanYadav</td><td>Fair alarm system working ok</td></tr><tr><td>08-02-2023 10:02:04</td><td>Ravi Rajbhar</td><td>Ppm done of fire panel, access door, epbax all system ok working done 3rd floor main door access divice of client side confirm to pradeep sir Security cabin fire panel check battery low</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-02-2023 02:46:16	ChandanYadav	Fair alarm system working ok	08-02-2023 10:02:04	Ravi Rajbhar	Ppm done of fire panel, access door, epbax all system ok working done 3rd floor main door access divice of client side confirm to pradeep sir Security cabin fire panel check battery low																
Date Time	Technician Name	Remark																												
13-02-2023 02:46:16	ChandanYadav	Fair alarm system working ok																												
08-02-2023 10:02:04	Ravi Rajbhar	Ppm done of fire panel, access door, epbax all system ok working done 3rd floor main door access divice of client side confirm to pradeep sir Security cabin fire panel check battery low																												