




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10137																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	28-11-2023 11:02:55																						
Vendor Details :																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
Address :																									
Mumbai , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	C-104 - When press the bell from outside, nothing is visible on the screen inside - 9167189075																								
Technician Comment :	C wing 104 video door phone issue resolved and ok working done duct side check																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	C wing 104 video door phone issue resolved and ok working done duct side check																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-11-2023 02:27:24</td><td>Ravi Rajbhar</td><td>Completed</td><td>C wing 104 video door phone issue resolved and ok working done duct side check</td><td></td></tr><tr><td>29-11-2023 10:13:37</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-11-2023 05:04:59</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-11-2023 02:27:24	Ravi Rajbhar	Completed	C wing 104 video door phone issue resolved and ok working done duct side check		29-11-2023 10:13:37	Ravi Rajbhar	New		-	28-11-2023 05:04:59	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
29-11-2023 02:27:24	Ravi Rajbhar	Completed	C wing 104 video door phone issue resolved and ok working done duct side check																						
29-11-2023 10:13:37	Ravi Rajbhar	New		-																					
28-11-2023 05:04:59	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-11-2023 10:15:37</td><td>Ravi Rajbhar</td><td>c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done</td></tr><tr><td>28-10-2023 04:45:30</td><td>Ravi Rajbhar</td><td>B 601 replacement against faulty install and ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-11-2023 10:15:37	Ravi Rajbhar	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done	28-10-2023 04:45:30	Ravi Rajbhar	B 601 replacement against faulty install and ok working done											
Date Time	Technician Name	Remark																							
29-11-2023 10:15:37	Ravi Rajbhar	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done																							
28-10-2023 04:45:30	Ravi Rajbhar	B 601 replacement against faulty install and ok working done																							