




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10147																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820606496																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	29-11-2023 10:15:37																	
Vendor Details :																				
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	C-103 vDP not working																			
Technician Comment :	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-11-2023 02:25:32</td><td>Ravi Rajbhar</td><td>Completed</td><td>c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done</td><td></td></tr><tr><td>29-11-2023 10:15:44</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-11-2023 02:25:32	Ravi Rajbhar	Completed	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done		29-11-2023 10:15:44	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-11-2023 02:25:32	Ravi Rajbhar	Completed	c wing 103 video door phone issue resolved and ok working done out site camera cable cut then reconnecting and ok working done																	
29-11-2023 10:15:44	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-11-2023 11:02:55</td><td>Ravi Rajbhar</td><td>C wing 104 video door phone issue resolved and ok working done duct side check</td></tr><tr><td>28-10-2023 04:45:30</td><td>Ravi Rajbhar</td><td>B 601 replacement against faulty install and ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-11-2023 11:02:55	Ravi Rajbhar	C wing 104 video door phone issue resolved and ok working done duct side check	28-10-2023 04:45:30	Ravi Rajbhar	B 601 replacement against faulty install and ok working done						
Date Time	Technician Name	Remark																		
28-11-2023 11:02:55	Ravi Rajbhar	C wing 104 video door phone issue resolved and ok working done duct side check																		
28-10-2023 04:45:30	Ravi Rajbhar	B 601 replacement against faulty install and ok working done																		