

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13430																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																					
Ticket Type :	Complain	Date & Time :	02-12-2024 11:49:09																						
Vendor Details :																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	B-101 Outdoor cameras need to install																								
Technician Comment :	New outdoor camera installed and repair indoor unit installed, now working both units normally.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	New outdoor camera installed and repair indoor unit installed, now working both units normally.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-12-2024 11:28:02</td><td>Rahul Mhapralkar</td><td>Completed</td><td>New outdoor camera installed and repair indoor unit installed, now working both units normally.</td><td></td></tr><tr><td>04-12-2024 10:32:52</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr><tr><td>02-12-2024 11:49:19</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-12-2024 11:28:02	Rahul Mhapralkar	Completed	New outdoor camera installed and repair indoor unit installed, now working both units normally.		04-12-2024 10:32:52	Rahul Mhapralkar	New		-	02-12-2024 11:49:19	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-12-2024 11:28:02	Rahul Mhapralkar	Completed	New outdoor camera installed and repair indoor unit installed, now working both units normally.																						
04-12-2024 10:32:52	Rahul Mhapralkar	New		-																					
02-12-2024 11:49:19	Rahul Mhapralkar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-12-2024 12:56:10</td><td>Siddhesh Chavan</td><td>Vdp issue resoved do not anabale issue resoved</td></tr><tr><td>25-11-2024 03:53:18</td><td>Siddhesh Chavan</td><td>Vdp reinstall done and working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-12-2024 12:56:10	Siddhesh Chavan	Vdp issue resoved do not anabale issue resoved	25-11-2024 03:53:18	Siddhesh Chavan	Vdp reinstall done and working ok											
Date Time	Technician Name	Remark																							
12-12-2024 12:56:10	Siddhesh Chavan	Vdp issue resoved do not anabale issue resoved																							
25-11-2024 03:53:18	Siddhesh Chavan	Vdp reinstall done and working ok																							