




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2259</b>																									
<b>Priority :</b>	High																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820606496																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	21-11-2020 10:55:36																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	vdp issue																								
<b>Technician Comment :</b>	c wing - 703 lobby video issue solved and all working ok 2) lobby panel is off and stated lobby panel and 1 st to 7 th floor video issue solved																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	c wing - 703 lobby video issue solved and all working ok 2) lobby panel is off and stated lobby panel and 1 st to 7 th floor video issue solved																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-11-2020 11:57:20</td><td>Siddhesh Chavan</td><td>Completed</td><td>c wing - 703 lobby video issue solved and all working ok 2) lobby panel is off and stated lobby panel and 1 st to 7 th floor video issue solved</td><td></td></tr><tr><td>21-11-2020 10:56:00</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-11-2020 10:55:36</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-11-2020 11:57:20	Siddhesh Chavan	Completed	c wing - 703 lobby video issue solved and all working ok 2) lobby panel is off and stated lobby panel and 1 st to 7 th floor video issue solved		21-11-2020 10:56:00	Siddhesh Chavan	New		-	21-11-2020 10:55:36	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-11-2020 11:57:20	Siddhesh Chavan	Completed	c wing - 703 lobby video issue solved and all working ok 2) lobby panel is off and stated lobby panel and 1 st to 7 th floor video issue solved																						
21-11-2020 10:56:00	Siddhesh Chavan	New		-																					
21-11-2020 10:55:36	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-11-2020 11:00:33</td><td>Neeraj Chauhan</td><td>repair and return vdp install and looby video satting done and b. wing 1901 1902 1001 lobby video issue solved</td></tr><tr><td>13-11-2020 10:44:09</td><td>MayurYadav</td><td>301 303 302 304 201 202 203 204 flat vdp install 101/102/104/1504/603 done 2nd floor debug done 103 pending interior work not complete</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-11-2020 11:00:33	Neeraj Chauhan	repair and return vdp install and looby video satting done and b. wing 1901 1902 1001 lobby video issue solved	13-11-2020 10:44:09	MayurYadav	301 303 302 304 201 202 203 204 flat vdp install 101/102/104/1504/603 done 2nd floor debug done 103 pending interior work not complete											
Date Time	Technician Name	Remark																							
20-11-2020 11:00:33	Neeraj Chauhan	repair and return vdp install and looby video satting done and b. wing 1901 1902 1001 lobby video issue solved																							
13-11-2020 10:44:09	MayurYadav	301 303 302 304 201 202 203 204 flat vdp install 101/102/104/1504/603 done 2nd floor debug done 103 pending interior work not complete																							