

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6093																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	30-07-2022 01:43:54																						
Vendor Details :																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	flat no c2202 screen need to change																								
Technician Comment :	c wing 2202 New sceen install and ok working done and 1900 cash collat and faulty sceen hondover to client																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	c wing 2202 New sceen install and ok working done and 1900 cash collat and faulty sceen hondover to client																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-07-2022 02:14:30</td><td>Ravi Rajbhar</td><td>Completed</td><td>c wing 2202 New sceen install and ok working done and 1900 cash collat and faulty sceen hondover to client</td><td></td></tr><tr><td>30-07-2022 01:44:11</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>30-07-2022 01:43:55</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-07-2022 02:14:30	Ravi Rajbhar	Completed	c wing 2202 New sceen install and ok working done and 1900 cash collat and faulty sceen hondover to client		30-07-2022 01:44:11	Ravi Rajbhar	New		-	30-07-2022 01:43:55	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-07-2022 02:14:30	Ravi Rajbhar	Completed	c wing 2202 New sceen install and ok working done and 1900 cash collat and faulty sceen hondover to client																						
30-07-2022 01:44:11	Ravi Rajbhar	New		-																					
30-07-2022 01:43:55	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-08-2022 01:58:34</td><td>Siddhesh Chavan</td><td>outdoor camera repair and return and install and working okay phone no = 9821696904</td></tr><tr><td>17-08-2022 01:57:39</td><td>Siddhesh Chavan</td><td>out door camera repair and ruten and install and working ok phone no = 9820731146</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-08-2022 01:58:34	Siddhesh Chavan	outdoor camera repair and return and install and working okay phone no = 9821696904	17-08-2022 01:57:39	Siddhesh Chavan	out door camera repair and ruten and install and working ok phone no = 9820731146											
Date Time	Technician Name	Remark																							
17-08-2022 01:58:34	Siddhesh Chavan	outdoor camera repair and return and install and working okay phone no = 9821696904																							
17-08-2022 01:57:39	Siddhesh Chavan	out door camera repair and ruten and install and working ok phone no = 9820731146																							