




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1258																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9221599700																								
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																					
Ticket Type :	New Installation	Date & Time :	28-02-2020 05:31:38																						
Vendor Details :																									
Company Name/Client Name :	Sulphur Mills	Customer's Mobile :	9221599700	Name :	Jagdish Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Projector																								
Complain :	install HDMI Extender																								
Technician Comment :	hdmi extender with rj 45 has been crimped at both sides in vimal sir cabin																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	hdmi extender with rj 45 has been crimped at both sides in vimal sir cabin																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-02-2020 08:52:34</td><td>YogeshDesai</td><td>Completed</td><td>hdmi extender with rj 45 has been crimped at both sides in vimal sir cabin</td><td></td></tr><tr><td>29-02-2020 01:47:36</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>28-02-2020 05:31:38</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-02-2020 08:52:34	YogeshDesai	Completed	hdmi extender with rj 45 has been crimped at both sides in vimal sir cabin		29-02-2020 01:47:36	YogeshDesai	New		-	28-02-2020 05:31:38	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
29-02-2020 08:52:34	YogeshDesai	Completed	hdmi extender with rj 45 has been crimped at both sides in vimal sir cabin																						
29-02-2020 01:47:36	YogeshDesai	New		-																					
28-02-2020 05:31:38	YogeshDesai	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-06-2022 12:06:51</td><td>Prashant Nikalje</td><td>visited on site 24.06.2022 - 1 camera offline 1 camera uninstalled client side.</td></tr><tr><td>20-11-2021 10:30:16</td><td>MayurYadav</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	28-06-2022 12:06:51	Prashant Nikalje	visited on site 24.06.2022 - 1 camera offline 1 camera uninstalled client side.	20-11-2021 10:30:16	MayurYadav												
Date Time	Technician Name	Remark																							
28-06-2022 12:06:51	Prashant Nikalje	visited on site 24.06.2022 - 1 camera offline 1 camera uninstalled client side.																							
20-11-2021 10:30:16	MayurYadav																								