

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13328															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	8591356528														
Technician Name :	Atique Salmani		Technician Mobile :	8080922984											
Ticket Type :	Complain	Date & Time :	21-11-2024 04:57:45												
Vendor Details :															
Company Name/Client Name :	Mahendra Realtors	Customer's Mobile :	8591356528	Name :	Jignesh Sir										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	VDP														
Complain :	B-902 VDP issue need to check														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>21-11-2024 04:57:51</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	21-11-2024 04:57:51	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign											
21-11-2024 04:57:51	Atique Salmani	New		-											
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>09-12-2024 10:43:52</td><td>MayurYadav</td><td>Great screen issue solve settings change</td></tr><tr><td>23-11-2024 07:03:26</td><td>Atique Salmani</td><td>Back side parking 206 start metr reding end 250 Maine gate start 305 start End 250 Back side parking and main gate parking area 2 cameras installation done with condute piping working ok.</td></tr></table>					Date Time	Technician Name	Remark	09-12-2024 10:43:52	MayurYadav	Great screen issue solve settings change	23-11-2024 07:03:26	Atique Salmani	Back side parking 206 start metr reding end 250 Maine gate start 305 start End 250 Back side parking and main gate parking area 2 cameras installation done with condute piping working ok.	
Date Time	Technician Name	Remark													
09-12-2024 10:43:52	MayurYadav	Great screen issue solve settings change													
23-11-2024 07:03:26	Atique Salmani	Back side parking 206 start metr reding end 250 Maine gate start 305 start End 250 Back side parking and main gate parking area 2 cameras installation done with condute piping working ok.													