







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8660																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9833857590																								
Technician Name :	Dilshad Khan		Technician Mobile :	9324177692																					
Ticket Type :	Complain	Date & Time :	24-06-2023 11:22:46																						
Vendor Details :																									
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	1 camera angle need to set																								
Technician Comment :	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-06-2023 01:15:50</td><td>DilshadKhan</td><td>Completed</td><td>1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve</td><td></td></tr><tr><td>24-06-2023 01:13:17</td><td>DilshadKhan</td><td>Completed</td><td>1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve</td><td></td></tr><tr><td>24-06-2023 11:23:29</td><td>DilshadKhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-06-2023 01:15:50	DilshadKhan	Completed	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve		24-06-2023 01:13:17	DilshadKhan	Completed	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve		24-06-2023 11:23:29	DilshadKhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-06-2023 01:15:50	DilshadKhan	Completed	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve																						
24-06-2023 01:13:17	DilshadKhan	Completed	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve																						
24-06-2023 11:23:29	DilshadKhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-06-2023 04:56:39</td><td>Kalpesh SubhashGurav</td><td>Main Gate Security Ext.99 Extra Ringer Installed OK</td></tr><tr><td>21-06-2023 04:51:47</td><td>Kalpesh SubhashGurav</td><td>A/1203 New Telephone Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-06-2023 04:56:39	Kalpesh SubhashGurav	Main Gate Security Ext.99 Extra Ringer Installed OK	21-06-2023 04:51:47	Kalpesh SubhashGurav	A/1203 New Telephone Installed Done.											
Date Time	Technician Name	Remark																							
21-06-2023 04:56:39	Kalpesh SubhashGurav	Main Gate Security Ext.99 Extra Ringer Installed OK																							
21-06-2023 04:51:47	Kalpesh SubhashGurav	A/1203 New Telephone Installed Done.																							