

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1210																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819121121																																		
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																															
Ticket Type :	Complain	Date & Time :	24-02-2020 10:49:53																																
Vendor Details :																																			
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	ram gali near bhalbharti CCTV VDP issue																																		
Technician Comment :	riten camera.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	riten camera.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-02-2020 05:08:07</td><td>Shiva Meena</td><td>Completed</td><td>riten camera.</td><td></td></tr><tr><td>24-02-2020 03:49:57</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>24-02-2020 03:45:30</td><td>Shiva Meena</td><td>Awaiting Spares</td><td>camera dome fauly collect for office check.</td><td></td></tr><tr><td>24-02-2020 10:50:00</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>24-02-2020 10:49:54</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-02-2020 05:08:07	Shiva Meena	Completed	riten camera.		24-02-2020 03:49:57	Shiva Meena	New		-	24-02-2020 03:45:30	Shiva Meena	Awaiting Spares	camera dome fauly collect for office check.		24-02-2020 10:50:00	Shiva Meena	New		-	24-02-2020 10:49:54	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																															
24-02-2020 05:08:07	Shiva Meena	Completed	riten camera.																																
24-02-2020 03:49:57	Shiva Meena	New		-																															
24-02-2020 03:45:30	Shiva Meena	Awaiting Spares	camera dome fauly collect for office check.																																
24-02-2020 10:50:00	Shiva Meena	New		-																															
24-02-2020 10:49:54	Shiva Meena	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-10-2020 10:59:14</td><td>Neeraj Chauhan</td><td></td></tr><tr><td>23-10-2020 10:35:39</td><td>Ravi Rajbhar</td><td>CCTV camera survey done 10 camera with cabling 250- 300 meter and raunak heights 406 vdp out door camera issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-10-2020 10:59:14	Neeraj Chauhan		23-10-2020 10:35:39	Ravi Rajbhar	CCTV camera survey done 10 camera with cabling 250- 300 meter and raunak heights 406 vdp out door camera issue resolved																					
Date Time	Technician Name	Remark																																	
24-10-2020 10:59:14	Neeraj Chauhan																																		
23-10-2020 10:35:39	Ravi Rajbhar	CCTV camera survey done 10 camera with cabling 250- 300 meter and raunak heights 406 vdp out door camera issue resolved																																	