

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10449</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9821069152																			
<b>Technician Name :</b>	Siddhesh Chavan	<b>Technician Mobile :</b>	8080922985																	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-01-2024 04:40:57																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Swapnalok CHS	<b>Customer's Mobile :</b>	9821069152	<b>Name :</b>	Kishor Bhai															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	31-05-2021 12:00:00	<b>Type :</b>	Comprehensive																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	Both lift camera connection need to do																			
<b>Technician Comment :</b>	Both lift camera working contion done by lift person and all camera working OK b wing lock fitting done and working OK																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Both lift camera working contion done by lift person and all camera working OK b wing lock fitting done and working OK																			
<b>Status History :</b>	<table border="1"><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-01-2024 02:59:55</td><td>Siddhesh Chavan</td><td>Completed</td><td>Both lift camera working contion done by lift person and all camera working OK b wing lock fitting done and working OK</td><td></td></tr><tr><td>06-01-2024 02:55:55</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-01-2024 02:59:55	Siddhesh Chavan	Completed	Both lift camera working contion done by lift person and all camera working OK b wing lock fitting done and working OK		06-01-2024 02:55:55	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
06-01-2024 02:59:55	Siddhesh Chavan	Completed	Both lift camera working contion done by lift person and all camera working OK b wing lock fitting done and working OK																	
06-01-2024 02:55:55	Siddhesh Chavan	New		-																
<b>Previous Complain History :</b>	<table border="1"><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-01-2024 06:46:01</td><td>MayurYadav</td><td>Tv on when visit</td></tr><tr><td>22-12-2023 10:56:56</td><td>Ravi Rajbhar</td><td>A wing 402 vdp and intercom issue resolved and ok working done B wing 701 vdp issue resolved and ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-01-2024 06:46:01	MayurYadav	Tv on when visit	22-12-2023 10:56:56	Ravi Rajbhar	A wing 402 vdp and intercom issue resolved and ok working done B wing 701 vdp issue resolved and ok working done						
Date Time	Technician Name	Remark																		
10-01-2024 06:46:01	MayurYadav	Tv on when visit																		
22-12-2023 10:56:56	Ravi Rajbhar	A wing 402 vdp and intercom issue resolved and ok working done B wing 701 vdp issue resolved and ok working done																		