## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \mathbf{W}: \text{www.vallabhenterprises.com} \\ \mathbf{E}: \text{vallabhsecure@yahoo.co.in}$ 

Service Status	Details: VE3486					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9820606496					
Technician Name :	Siddhesh Chavan			Technician Mobile :	8080922985	
Ticket Type :	Complain	Date & T	ime :	23-07-2021 05:23:23		
Vendor Details	s:	_				
Company Name/Client Name :	Samet Sikhar Mahal Society	Customer's Mobile :		9820606496	Name :	Kothari
Address :		•				
Mumbai,,,,	Maharashtra					
AMC Details:						
Expiry Date :	01-01-1970 05:30:00		Type:			
Product Name :	VDP					
Complain:	Voice issue in all flats					
Technician Comment :	power supply at 9th floor swipe with power supply at 15th floor 9th floor distributor pcb change flat check $201/703/903/804/1002/1702/1802/1902$ all working ok keep under observation					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	power supply at 9th floor swipe with power supply at 15th floor 9th floor distributor pcb change flat check 201/703/903/804/1002/1702/1802/1902 all working ok keep under observation					
Status History :	Date Time	Technician Name	Status	Remark		Sign
						Sign
	24-07-2021 01:21:23	Siddhesh Chavan	Completed	power supply at 9th floor supply at 15th floor 9th floor change flat check 201/703/903/804/1002/17 working ok keep under ok	oor distributor pcb 02/1802/1902 all	
			Completed  Work Pending	supply at 15th floor 9th flohange flat check 201/703/903/804/1002/17	oor distributor pcb 02/1802/1902 all oservation or phone calling ok	Jun 7
	01:21:23	Chavan Siddhesh	Work	supply at 15th floor 9th flohange flat check 201/703/903/804/1002/17 working ok keep under oh 1 st floor to 8 th video doo	oor distributor pcb 02/1802/1902 all oservation or phone calling ok	Jun 7
	23-07-2021 07:04:24	Chavan  Siddhesh Chavan  Siddhesh	Work Pending	supply at 15th floor 9th flohange flat check 201/703/903/804/1002/17 working ok keep under oh 1 st floor to 8 th video doo	oor distributor pcb 02/1802/1902 all oservation or phone calling ok	Jun 7
Previous	23-07-2021 07:04:24 23-07-2021 05:25:29 23-07-2021 05:23:23	Siddhesh Chavan Siddhesh Chavan Siddhesh Chavan	Work Pending New	supply at 15th floor 9th flohange flat check 201/703/903/804/1002/17 working ok keep under oh 1 st floor to 8 th video doo	oor distributor pcb 02/1802/1902 all oservation or phone calling ok	Jun 7
Previous Complain History :	23-07-2021 07:04:24 23-07-2021 05:25:29 23-07-2021	Siddhesh Chavan Siddhesh Chavan Siddhesh Chavan	Work Pending New	supply at 15th floor 9th flohange flat check 201/703/903/804/1002/17 working ok keep under oh  1 st floor to 8 th video dog and 9 floor to 18 floor per	poor distributor pcb 02/1802/1902 all oservation or phone calling ok dding  Remark	Jun 7