

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10226																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Ishwar Meena		Technician Mobile :	9165341500																
Ticket Type :	New Installation	Date & Time :	09-12-2023 10:40:27																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	crimping work pending																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-12-2023 10:04:46</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>09-12-2023 10:40:33</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-12-2023 10:04:46	Ishwar Meena	New		-	09-12-2023 10:40:33	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
16-12-2023 10:04:46	Ishwar Meena	New		-																
09-12-2023 10:40:33	Ishwar Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-12-2023 05:41:25</td><td>Sonu Kumar</td><td>Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok</td></tr><tr><td>15-12-2023 04:42:37</td><td>Ishwar Meena</td><td>(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok	15-12-2023 04:42:37	Ishwar Meena	(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.						
Date Time	Technician Name	Remark																		
20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok																		
15-12-2023 04:42:37	Ishwar Meena	(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.																		