




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10272																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9930943918																								
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																					
Ticket Type :	Complain	Date & Time :	14-12-2023 01:26:17																						
Vendor Details :																									
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	1st floor DVR 157 camera cable joint issue																								
Technician Comment :	1st floor camera no 11 new cabling camera off issue resolved and 1st floor classroom 3 1ip camera and 1 passage camera swiftng done																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1st floor camera no 11 new cabling camera off issue resolved and 1st floor classroom 3 1ip camera and 1 passage camera swiftng done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-12-2023 02:25:32</td><td>Sonu Kumar</td><td>Completed</td><td>1st floor camera no 11 new cabling camera off issue resolved and 1st floor classroom 3 1ip camera and 1 passage camera swiftng done</td><td></td></tr><tr><td>21-12-2023 10:12:53</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>16-12-2023 10:04:38</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-12-2023 02:25:32	Sonu Kumar	Completed	1st floor camera no 11 new cabling camera off issue resolved and 1st floor classroom 3 1ip camera and 1 passage camera swiftng done		21-12-2023 10:12:53	Sonu Kumar	New		-	16-12-2023 10:04:38	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-12-2023 02:25:32	Sonu Kumar	Completed	1st floor camera no 11 new cabling camera off issue resolved and 1st floor classroom 3 1ip camera and 1 passage camera swiftng done																						
21-12-2023 10:12:53	Sonu Kumar	New		-																					
16-12-2023 10:04:38	Sonu Kumar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-12-2023 05:41:25</td><td>Sonu Kumar</td><td>Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok</td></tr><tr><td>15-12-2023 04:42:37</td><td>Ishwar Meena</td><td>(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok	15-12-2023 04:42:37	Ishwar Meena	(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.											
Date Time	Technician Name	Remark																							
20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok																							
15-12-2023 04:42:37	Ishwar Meena	(1)1st floor (room no.3 out of gate) passage camera cable 235 - 208 =27 mtr (2) 16 nos RJ45 conector cropping done. (3) 6th floor new hall(small and big dono) all cmera clean with housing (4) 3rd floor one camera issue resolved. (5) 5th floor 5 camera issue resolved (6) 6th floor new hall all camera angle set. Work completed.																							