




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11254																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	28-03-2024 03:26:51																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	1st and 3rd floor DVR beep sound issue																			
Technician Comment :	1st floor beep sound issue resolved by one camera ground floor off adaptor installed on 1st floor zicom junction box seprate adaptor for this camera need to from rack supply cabling need to do 40 50 meter approx and also check also 3rd floor one office side lift camera off from 12 March and also lift off need to check with David sir or lift person .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1st floor beep sound issue resolved by one camera ground floor off adaptor installed on 1st floor zicom junction box seprate adaptor for this camera need to from rack supply cabling need to do 40 50 meter approx and also check also 3rd floor one office side lift camera off from 12 March and also lift off need to check with David sir or lift person .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-03-2024 03:46:14</td><td>Atique Salmani</td><td>Completed</td><td>1st floor beep sound issue resolved by one camera ground floor off adaptor installed on 1st floor zicom junction box seprate adaptor for this camera need to from rack supply cabling need to do 40 50 meter approx and also check also 3rd floor one office side lift camera off from 12 March and also lift off need to check with David sir or lift person .</td><td></td></tr><tr><td>29-03-2024 10:09:43</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-03-2024 03:46:14	Atique Salmani	Completed	1st floor beep sound issue resolved by one camera ground floor off adaptor installed on 1st floor zicom junction box seprate adaptor for this camera need to from rack supply cabling need to do 40 50 meter approx and also check also 3rd floor one office side lift camera off from 12 March and also lift off need to check with David sir or lift person .		29-03-2024 10:09:43	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-03-2024 03:46:14	Atique Salmani	Completed	1st floor beep sound issue resolved by one camera ground floor off adaptor installed on 1st floor zicom junction box seprate adaptor for this camera need to from rack supply cabling need to do 40 50 meter approx and also check also 3rd floor one office side lift camera off from 12 March and also lift off need to check with David sir or lift person .																	
29-03-2024 10:09:43	Atique Salmani	New		-																

Previous Complain History :			
	Date Time	Technician Name	Remark
	26-03-2024 02:30:34	Siddhesh Chavan	bus no 10 all camera working ok and bus no 1 dvr install and date time ok
	26-03-2024 11:20:24	Siddhesh Chavan	kg section 6 cameras working ok