

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7868																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	Complain	Date & Time :	15-03-2023 10:40:52																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	ground area 1 camera damage need to do check																			
Technician Comment :	Ground area damage camer aneed to change hikvision bulet camera 1 4×4 box																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Ground area damage camer aneed to change hikvision bulet camera 1 4×4 box																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-03-2023 10:58:49</td><td>Sonu Kumar</td><td>Completed</td><td>Ground area damage camer aneed to change hikvision bulet camera 1 4×4 box</td><td></td></tr><tr><td>15-03-2023 10:41:04</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-03-2023 10:58:49	Sonu Kumar	Completed	Ground area damage camer aneed to change hikvision bulet camera 1 4×4 box		15-03-2023 10:41:04	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
15-03-2023 10:58:49	Sonu Kumar	Completed	Ground area damage camer aneed to change hikvision bulet camera 1 4×4 box																	
15-03-2023 10:41:04	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-03-2023 10:55:30</td><td>Ravi Rajbhar</td><td>back side gate new hd bullet camera install with angle setting done and one camera shift back side passege</td></tr><tr><td>08-03-2023 11:46:11</td><td>Siddhesh Chavan</td><td>12 no bus dvr take to office for checking and ground floor 1 camera angel satting done</td></tr></tbody></table>					Date Time	Technician Name	Remark	18-03-2023 10:55:30	Ravi Rajbhar	back side gate new hd bullet camera install with angle setting done and one camera shift back side passege	08-03-2023 11:46:11	Siddhesh Chavan	12 no bus dvr take to office for checking and ground floor 1 camera angel satting done						
Date Time	Technician Name	Remark																		
18-03-2023 10:55:30	Ravi Rajbhar	back side gate new hd bullet camera install with angle setting done and one camera shift back side passege																		
08-03-2023 11:46:11	Siddhesh Chavan	12 no bus dvr take to office for checking and ground floor 1 camera angel satting done																		