Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : vallabhsecure@ya	11100.00.111					
Service Status D	etails : VE8659					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9930943918					
Technician Name :	Siddhesh Chavan		Technic:	ian Mobile	8080922985	
Ticket Type :	Complain	Date & Time :	24-06-20)23 11:11:17		
Vendor Details :			_			
Company Name/Client Name :	St Joseph	Customer's Mobil :	le 9930943	3918	Name :	Levon
Address:						
Mumbai , , , , M	aharashtra					
AMC Details:						
Expiry Date :	31-03-2021 12:00:00		Type:		Non-Comprehensive	
Product Name:	CCTV					
Complain :	Bus no 11 Beep sound Bus no 8 Holder Bus no 10 Red indicator 1st floor need to install audio camera location need to check					
Technician Comment :	bus no 11 DVR working OK bus no 8 camera take to office for checking bus no 10 red indicator a power and DVR working OK bus no one dome camera take to office for checking 1 st floor one DVR beep sound issue resoved 5 th floor nvr beep sound issue resolved 1 st floor class room no 4 need to do cabling and install mic 8 port Poe switch take to office for checking					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	bus no 11 DVR working OK bus no 8 camera take to office for checking bus no 10 red indicator a power and DVR working OK bus no one dome camera take to office for checking 1 st floor one DVR beep sound issue resoved 5 th floor nvr beep sound issue resolved 1 st floor class room no 4 need to do cabling and install mic 8 port Poe switch take to office for checking					
Status History :	Date Time	Technician Name	Status		Remark	Sign
	26-06-2023 12:18:30	Siddhesh Chavan	Work Pending	camera take to bus no 10 red DVR working camera take to st floor one D resoved 5 th to issue resolved no 4 need to to the bus no 4 need to the bus no 10 need to the bus need to	R working OK bus no to office for checking I indicator a power an OK bus no one dome to office for checking VR beep sound issue floor nvr beep sound d 1 st floor class room do cabling and install e switch take to office	d 1
	26-06-2023 11:14:50	Siddhesh Chavan	New			
	24-06-2023 11:12:19	Siddhesh Chavan	New			-

Previous
Complain
History :

Date Time	Technician Name	Remark
17-08-2023 01:06:57	Ravi Rajbhar	1st floor dvr - 157 camera number 07 no video issue relsoved and ok working done only dvr side bnc pin reconneted propely and banglow side one camera swape confrim to levon sir
12-08-2023 02:33:06	Ravi Rajbhar	