

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3203																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9082191817																								
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																					
Ticket Type :	Complain	Date & Time :	07-06-2021 11:15:45																						
Vendor Details :																									
Company Name/Client Name :	Almond & Alcacia - Mahavir Kalpavruksh H&I Wing	Customer's Mobile :	9082191817	Name :	Madhu Madam																				
Address :																									
thane , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	almond - 1103 vdp complain i wing - 504 camera install after repaired																								
Technician Comment :	I wing 504 outdoor camera install done and 1103 door door phone complaint solve work.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	I wing 504 outdoor camera install done and 1103 door door phone complaint solve work.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-06-2021 05:44:36</td><td>Neeraj Chauhan</td><td>Completed</td><td>I wing 504 outdoor camera install done and 1103 door door phone complaint solve work.</td><td></td></tr><tr><td>07-06-2021 11:15:57</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>07-06-2021 11:15:45</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-06-2021 05:44:36	Neeraj Chauhan	Completed	I wing 504 outdoor camera install done and 1103 door door phone complaint solve work.		07-06-2021 11:15:57	Neeraj Chauhan	New		-	07-06-2021 11:15:45	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
09-06-2021 05:44:36	Neeraj Chauhan	Completed	I wing 504 outdoor camera install done and 1103 door door phone complaint solve work.																						
07-06-2021 11:15:57	Neeraj Chauhan	New		-																					
07-06-2021 11:15:45	Neeraj Chauhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-06-2023 10:38:47</td><td>DilshadKhan</td><td>Lift camera issu Resolved and solve</td></tr><tr><td>29-05-2023 10:56:43</td><td>SantoshPathak</td><td>dilshad visited site 29.05.2023 1 camera issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-06-2023 10:38:47	DilshadKhan	Lift camera issu Resolved and solve	29-05-2023 10:56:43	SantoshPathak	dilshad visited site 29.05.2023 1 camera issue resolved											
Date Time	Technician Name	Remark																							
12-06-2023 10:38:47	DilshadKhan	Lift camera issu Resolved and solve																							
29-05-2023 10:56:43	SantoshPathak	dilshad visited site 29.05.2023 1 camera issue resolved																							