




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1558																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9742015015																								
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																					
Ticket Type :	Complain	Date & Time :	14-07-2020 12:36:16																						
Vendor Details :																									
Company Name/Client Name :	Concentrix Services India Private Limited - MT	Customer's Mobile :	9742015015	Name :	Madhu Sir-Mt																				
Address :																									
Bangalore , , , 560037 , Karnataka																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	On 14th July 20 We have observed that 2nd floor AV camera voice is not clear. Kindly look in to this issue on priority .																								
Technician Comment :	noise in AC camera due to background noise of AC near AV camera																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	noise in AC camera due to background noise of AC near AV camera																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-07-2020 06:43:10</td><td>MayurYadav</td><td>Completed</td><td>noise in AC camera due to background noise of AC near AV camera</td><td></td></tr><tr><td>14-07-2020 12:39:56</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>14-07-2020 12:36:17</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-07-2020 06:43:10	MayurYadav	Completed	noise in AC camera due to background noise of AC near AV camera		14-07-2020 12:39:56	MayurYadav	New		-	14-07-2020 12:36:17	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
14-07-2020 06:43:10	MayurYadav	Completed	noise in AC camera due to background noise of AC near AV camera																						
14-07-2020 12:39:56	MayurYadav	New		-																					
14-07-2020 12:36:17	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-10-2020 08:49:57</td><td>YashDoshi</td><td></td></tr><tr><td>19-10-2020 12:43:41</td><td>YashDoshi</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	20-10-2020 08:49:57	YashDoshi		19-10-2020 12:43:41	YashDoshi												
Date Time	Technician Name	Remark																							
20-10-2020 08:49:57	YashDoshi																								
19-10-2020 12:43:41	YashDoshi																								