




B K Infotech

Regd. Office : 506 Swapna Siddhi, Akurli Road, kandivali East Mumbai - 400 064, India.
Support : | W : <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1006																									
Priority :	High																								
Created By :	Admin - Kalpesh Jain																								
Complaint Mob. No. :	9322212433																								
Technician Name :	Mayur Pitale		Technician Mobile :	9136841703																					
Ticket Type :	Complain	Date & Time :	25-09-2019 01:14:34																						
Vendor Details :																									
Company Name/Client Name :	Mamta Metal	Customer's Mobile :	9322212433	Name :	Mamta Metal																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Computer																								
Complain :	issue in machine																								
Technician Comment :	mamta metal system problem solved by cleaning carbon from hdd connector machin is working fine now checked rishabh																								
Complain Operator :	Desktop - Kalpesh Jain																								
Remark :	mamta metal system problem solved by cleaning carbon from hdd connector machin is working fine now checked rishabh																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-09-2019 02:22:43</td><td>Mayur Pitale</td><td>Completed</td><td>mamta metal system problem solved by cleaning carbon from hdd connector machin is working fine now checked rishabh</td><td></td></tr><tr><td>25-09-2019 01:14:38</td><td>Mayur Pitale</td><td>New</td><td></td><td>-</td></tr><tr><td>25-09-2019 01:14:34</td><td>Mayur Pitale</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-09-2019 02:22:43	Mayur Pitale	Completed	mamta metal system problem solved by cleaning carbon from hdd connector machin is working fine now checked rishabh		25-09-2019 01:14:38	Mayur Pitale	New		-	25-09-2019 01:14:34	Mayur Pitale	New		-
Date Time	Technician Name	Status	Remark	Sign																					
25-09-2019 02:22:43	Mayur Pitale	Completed	mamta metal system problem solved by cleaning carbon from hdd connector machin is working fine now checked rishabh																						
25-09-2019 01:14:38	Mayur Pitale	New		-																					
25-09-2019 01:14:34	Mayur Pitale	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-11-2019 05:08:00</td><td>ShubhamBhojne</td><td>pc servicing completed</td></tr><tr><td>10-09-2019 05:48:12</td><td>ShubhamBhojne</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	06-11-2019 05:08:00	ShubhamBhojne	pc servicing completed	10-09-2019 05:48:12	ShubhamBhojne												
Date Time	Technician Name	Remark																							
06-11-2019 05:08:00	ShubhamBhojne	pc servicing completed																							
10-09-2019 05:48:12	ShubhamBhojne																								