

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15142																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9825048345																													
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																										
Ticket Type :	New Installation	Date & Time :	30-06-2025 03:05:20																											
Vendor Details :																														
Company Name/Client Name :	Maharaja Rajendrasingji CHS	Customer's Mobile :	9825048345	Name :	Manvendra Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Intercom																													
Complain :	old system need to install																													
Technician Comment :	system cakble punch and all falt not working intercom. cakble not properly in falt.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	system cakble punch and all falt not working intercom. cakble not properly in falt.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-07-2025 03:57:19</td><td>ChandanYadav</td><td>Completed</td><td></td><td>-</td></tr><tr><td>05-07-2025 01:06:54</td><td>ChandanYadav</td><td>Work Pending</td><td>system cakble punch and all falt not working intercom. cakble not properly in falt.</td><td></td></tr><tr><td>05-07-2025 10:13:36</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>05-07-2025 09:53:00</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-07-2025 03:57:19	ChandanYadav	Completed		-	05-07-2025 01:06:54	ChandanYadav	Work Pending	system cakble punch and all falt not working intercom. cakble not properly in falt.		05-07-2025 10:13:36	ChandanYadav	New		-	05-07-2025 09:53:00	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																										
17-07-2025 03:57:19	ChandanYadav	Completed		-																										
05-07-2025 01:06:54	ChandanYadav	Work Pending	system cakble punch and all falt not working intercom. cakble not properly in falt.																											
05-07-2025 10:13:36	ChandanYadav	New		-																										
05-07-2025 09:53:00	ChandanYadav	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-07-2025 01:25:12</td><td>Ravi Rajbhar</td><td>Flat no. 14 - door lock 13 - ok working done 12 - ok working done 11 - client told remove instument 10 - not used intercom 9 - door lock 8 - ok working done 7 - ok working 6 - door lock 5 - ok working 4 / 3 - not used phone 2 - ok working done 1 - door lock Security table display data and time set</td></tr><tr><td>23-06-2025 12:24:54</td><td>Ravi Rajbhar</td><td>Intercom survey done 5 floor juction and 2nd floor new equipment crown model 2 box 2 (10 pair ya 20 pair)</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-07-2025 01:25:12	Ravi Rajbhar	Flat no. 14 - door lock 13 - ok working done 12 - ok working done 11 - client told remove instument 10 - not used intercom 9 - door lock 8 - ok working done 7 - ok working 6 - door lock 5 - ok working 4 / 3 - not used phone 2 - ok working done 1 - door lock Security table display data and time set	23-06-2025 12:24:54	Ravi Rajbhar	Intercom survey done 5 floor juction and 2nd floor new equipment crown model 2 box 2 (10 pair ya 20 pair)																
Date Time	Technician Name	Remark																												
14-07-2025 01:25:12	Ravi Rajbhar	Flat no. 14 - door lock 13 - ok working done 12 - ok working done 11 - client told remove instument 10 - not used intercom 9 - door lock 8 - ok working done 7 - ok working 6 - door lock 5 - ok working 4 / 3 - not used phone 2 - ok working done 1 - door lock Security table display data and time set																												
23-06-2025 12:24:54	Ravi Rajbhar	Intercom survey done 5 floor juction and 2nd floor new equipment crown model 2 box 2 (10 pair ya 20 pair)																												