

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12171															
Priority :		Low													
Created By :		Admin - Apurva Vajaria													
Complaint Mob. No. :		9833222801													
Technician Name :		Ravi Rajbhar		Technician Mobile :	8080922965										
Ticket Type :		Complain	Date & Time :	17-07-2024 04:25:09											
Vendor Details :															
Company Name/Client Name :		Poonam Cluster	Customer's Mobile :	9833222801	Name : Mateen Sir										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :		01-01-1970 05:30:00		Type :											
Product Name :		Access													
Complain :		gate no. 2 both boom barriers are not working													
Technician Comment :															
Complain Operator :		Desktop - Apurva Vajaria													
Remark :															
Status History :		<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>23-07-2024 10:50:02</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></table>				Date Time	Technician Name	Status	Remark	Sign	23-07-2024 10:50:02	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign											
23-07-2024 10:50:02	Ravi Rajbhar	New		-											
Previous Complain History :		<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>07-10-2024 05:30:01</td><td>Sonu Kumar</td><td></td></tr><tr><td>04-10-2024 04:55:56</td><td>Shiva Meena</td><td>30 miter cabling work done and camera reinstall done work completed</td></tr></table>				Date Time	Technician Name	Remark	07-10-2024 05:30:01	Sonu Kumar		04-10-2024 04:55:56	Shiva Meena	30 miter cabling work done and camera reinstall done work completed	
Date Time	Technician Name	Remark													
07-10-2024 05:30:01	Sonu Kumar														
04-10-2024 04:55:56	Shiva Meena	30 miter cabling work done and camera reinstall done work completed													