

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8821																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820954001																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	12-07-2023 03:05:38																	
Vendor Details :																				
Company Name/Client Name :	Ismaili Delta Jamatkhana (Mira Road East)	Customer's Mobile :	9820954001	Name :	Mehendi Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	IP Camera 2-3 camera water inserted fog issue and 2-3 cameras off issue but where installed not found																			
Technician Comment :	B4 gate side camera ok cable faulty so camera swap on main gate working ok Cable required approx 150 metr .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	B4 gate side camera ok cable faulty so camera swap on main gate working ok Cable required approx 150 metr .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-07-2023 03:28:15</td><td>Atique Salmani</td><td>Completed</td><td>B4 gate side camera ok cable faulty so camera swap on main gate working ok Cable required approx 150 metr .</td><td></td></tr><tr><td>12-07-2023 03:06:05</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-07-2023 03:28:15	Atique Salmani	Completed	B4 gate side camera ok cable faulty so camera swap on main gate working ok Cable required approx 150 metr .		12-07-2023 03:06:05	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-07-2023 03:28:15	Atique Salmani	Completed	B4 gate side camera ok cable faulty so camera swap on main gate working ok Cable required approx 150 metr .																	
12-07-2023 03:06:05	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead></table>					Date Time	Technician Name	Remark												
Date Time	Technician Name	Remark																		