




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8746																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930599478																			
Technician Name :	Ishwar Meena		Technician Mobile :	9165341500																
Ticket Type :	Complain	Date & Time :	05-07-2023 10:01:19																	
Vendor Details :																				
Company Name/Client Name :	St Anthony Church	Customer's Mobile :	9930599478	Name :	Minino D'souza															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	29-11-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	cameras need to shift first need to do survey and some cameras angle need to set																			
Technician Comment :	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2023 12:23:15</td><td>Ishwar Meena</td><td>Completed</td><td>(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.</td><td></td></tr><tr><td>05-07-2023 10:01:29</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2023 12:23:15	Ishwar Meena	Completed	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.		05-07-2023 10:01:29	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-07-2023 12:23:15	Ishwar Meena	Completed	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.																	
05-07-2023 10:01:29	Ishwar Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-07-2023 11:04:50</td><td>Kalpesh SubhashGurav</td><td>Church Back Side Camera Shifting Done.</td></tr><tr><td>24-07-2023 10:53:21</td><td>Kalpesh SubhashGurav</td><td>Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-07-2023 11:04:50	Kalpesh SubhashGurav	Church Back Side Camera Shifting Done.	24-07-2023 10:53:21	Kalpesh SubhashGurav	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine						
Date Time	Technician Name	Remark																		
25-07-2023 11:04:50	Kalpesh SubhashGurav	Church Back Side Camera Shifting Done.																		
24-07-2023 10:53:21	Kalpesh SubhashGurav	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine																		