

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8950</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9930599478																			
<b>Technician Name :</b>	Kalpesh Subhash Gurav		<b>Technician Mobile :</b>	8879684054																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	24-07-2023 10:53:21																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	St Anthony Church	Customer's Mobile :	9930599478	Name :	Minino D'souza															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	29-11-2020 12:00:00		Type :	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	change of position of one of the cameras in the sacristy and Biometric off issue change of position of one of the cameras in the sacristy and Biometric off issue																			
<b>Technician Comment :</b>	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-07-2023 02:13:27</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine</td><td>शनि</td></tr><tr><td>24-07-2023 10:53:36</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-07-2023 02:13:27	Kalpesh SubhashGurav	Completed	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine	शनि	24-07-2023 10:53:36	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-07-2023 02:13:27	Kalpesh SubhashGurav	Completed	Church Office Biometric Problem Solved Church 1 Camera Shifting Required 3 meter cable and Drilling Machine	शनि																
24-07-2023 10:53:36	Kalpesh SubhashGurav	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-07-2023 11:04:50</td><td>Kalpesh SubhashGurav</td><td>Church Back Side Camera Shifting Done.</td></tr><tr><td>05-07-2023 10:01:19</td><td>Ishwar Meena</td><td>(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-07-2023 11:04:50	Kalpesh SubhashGurav	Church Back Side Camera Shifting Done.	05-07-2023 10:01:19	Ishwar Meena	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.						
Date Time	Technician Name	Remark																		
25-07-2023 11:04:50	Kalpesh SubhashGurav	Church Back Side Camera Shifting Done.																		
05-07-2023 10:01:19	Ishwar Meena	(1) one camera sifted working ok. (2) 2 person fingers add done. (3) 3 camera angle set working ok. (4) Biomax before off,, after on today working ok.																		