




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4259</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9223207875																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-11-2021 03:13:07																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	9223207875	Name :	Nandu Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	5th floor 6 fisheye camera need to shift																								
<b>Technician Comment :</b>	one fish eye camerainstalled with pole and working with ok shifting painting .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	one fish eye camerainstalled with pole and working with ok shifting painting .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-11-2021 06:11:30</td><td>Atique Salmani</td><td>Completed</td><td>one fish eye camerainstalled with pole and working with ok shifting painting .</td><td></td></tr><tr><td>20-11-2021 03:13:28</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>20-11-2021 03:13:07</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-11-2021 06:11:30	Atique Salmani	Completed	one fish eye camerainstalled with pole and working with ok shifting painting .		20-11-2021 03:13:28	Atique Salmani	New		-	20-11-2021 03:13:07	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-11-2021 06:11:30	Atique Salmani	Completed	one fish eye camerainstalled with pole and working with ok shifting painting .																						
20-11-2021 03:13:28	Atique Salmani	New		-																					
20-11-2021 03:13:07	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-11-2021 11:28:31</td><td>Siddhesh Chavan</td><td>3 NVR set time issue resolved all camera working ok</td></tr><tr><td>30-10-2021 10:40:48</td><td>Ravi Rajbhar</td><td>3r floor 8-9 fisheye camera angles setting done all ok working NVR recording check 28/aug /21 to 30/Oct/21 second NVR 18/sept/21 to 30/Oct/21 going on in both NVR</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-11-2021 11:28:31	Siddhesh Chavan	3 NVR set time issue resolved all camera working ok	30-10-2021 10:40:48	Ravi Rajbhar	3r floor 8-9 fisheye camera angles setting done all ok working NVR recording check 28/aug /21 to 30/Oct/21 second NVR 18/sept/21 to 30/Oct/21 going on in both NVR											
Date Time	Technician Name	Remark																							
15-11-2021 11:28:31	Siddhesh Chavan	3 NVR set time issue resolved all camera working ok																							
30-10-2021 10:40:48	Ravi Rajbhar	3r floor 8-9 fisheye camera angles setting done all ok working NVR recording check 28/aug /21 to 30/Oct/21 second NVR 18/sept/21 to 30/Oct/21 going on in both NVR																							