




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE557																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9223207875																								
Technician Name :	Anil Yadav		Technician Mobile :	8080922983																					
Ticket Type :	Complain	Date & Time :	18-10-2019 12:02:09																						
Vendor Details :																									
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	9223207875	Name :	Nandu Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Time And Attendance																								
Complain :	download utility																								
Technician Comment :	Repaired biimetric device installed.proper working condition now. device location is 3rd floor server room.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Repaired biimetric device installed.proper working condition now. device location is 3rd floor server room.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-11-2019 11:47:03</td><td>AnilYadav</td><td>Completed</td><td>Repaired biimetric device installed.proper working condition now. device location is 3rd floor server room.</td><td></td></tr><tr><td>05-11-2019 10:12:36</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>18-10-2019 12:02:10</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-11-2019 11:47:03	AnilYadav	Completed	Repaired biimetric device installed.proper working condition now. device location is 3rd floor server room.		05-11-2019 10:12:36	AnilYadav	New		-	18-10-2019 12:02:10	AnilYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-11-2019 11:47:03	AnilYadav	Completed	Repaired biimetric device installed.proper working condition now. device location is 3rd floor server room.																						
05-11-2019 10:12:36	AnilYadav	New		-																					
18-10-2019 12:02:10	AnilYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-10-2019 03:51:15</td><td>YashDoshi</td><td></td></tr><tr><td>25-09-2019 10:57:08</td><td>AnilYadav</td><td>NVR number 2 mouse not working issue and NVR 3 not proper view issue resolved. All 3 NVR properly working condition now</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-10-2019 03:51:15	YashDoshi		25-09-2019 10:57:08	AnilYadav	NVR number 2 mouse not working issue and NVR 3 not proper view issue resolved. All 3 NVR properly working condition now											
Date Time	Technician Name	Remark																							
17-10-2019 03:51:15	YashDoshi																								
25-09-2019 10:57:08	AnilYadav	NVR number 2 mouse not working issue and NVR 3 not proper view issue resolved. All 3 NVR properly working condition now																							