




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12511																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821036391																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	23-08-2024 10:47:04																	
Vendor Details :																				
Company Name/Client Name :	Petit Tower CHS Ltd	Customer's Mobile :	9821036391	Name :	Naozer Baldawala															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	flat no. 602 intercom out calling issue																			
Technician Comment :	flat no .602 line ok instrument issue need to change instrument																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	flat no .602 line ok instrument issue need to change instrument																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-08-2024 02:58:44</td><td>Ravi Rajbhar</td><td>Completed</td><td>flat no .602 line ok instrument issue need to change instrument</td><td></td></tr><tr><td>26-08-2024 11:27:33</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-08-2024 02:58:44	Ravi Rajbhar	Completed	flat no .602 line ok instrument issue need to change instrument		26-08-2024 11:27:33	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
26-08-2024 02:58:44	Ravi Rajbhar	Completed	flat no .602 line ok instrument issue need to change instrument																	
26-08-2024 11:27:33	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-08-2024 11:28:50</td><td>Ravi Rajbhar</td><td>flat no. 402 intercom issue resolved flat no.2101 intercom issue resolved flat no. 301 door lock flat no. 602 line ok instrument issue</td></tr><tr><td>03-08-2024 04:57:50</td><td>Ravi Rajbhar</td><td>flat no. 2101 or 2201 already ok working done confirm to client and flat no. 2201 no instrument confirm to clients</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-08-2024 11:28:50	Ravi Rajbhar	flat no. 402 intercom issue resolved flat no.2101 intercom issue resolved flat no. 301 door lock flat no. 602 line ok instrument issue	03-08-2024 04:57:50	Ravi Rajbhar	flat no. 2101 or 2201 already ok working done confirm to client and flat no. 2201 no instrument confirm to clients						
Date Time	Technician Name	Remark																		
26-08-2024 11:28:50	Ravi Rajbhar	flat no. 402 intercom issue resolved flat no.2101 intercom issue resolved flat no. 301 door lock flat no. 602 line ok instrument issue																		
03-08-2024 04:57:50	Ravi Rajbhar	flat no. 2101 or 2201 already ok working done confirm to client and flat no. 2201 no instrument confirm to clients																		